

Humble Service Station
Southwest corner of 26th Street and
Pennsylvania Avenue, NW
Washington
District of Columbia

HABS No. DC-319

HABS
DC,
WASH,
450-

PHOTOGRAPH

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

ARCHITECTURAL DATA FORM

STATE District of Columbia	COUNTY	TOWN OR VICINITY Washington
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Humble Service Station		HABS NO. DC-319
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Southwest corner 26th Street and Pennsylvania Avenue, NW		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1930's	ARCHITECT(S) (INCLUDE SOURCE)	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Interesting example of early gas station design.		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) 1- story		
EXTERIOR FEATURES OF NOTE Tile hipped roof with deck; west end enclosed to form office; east end supported by 2 brick columns; remainder is open and shelters gasoline pumps and driveways		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Demolished 1970.		
PRESENT CONDITION AND USE		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Schwartz, Nancy B. <u>Historic American Buildings Survey District of Columbia Catalog, 1974.</u>		
COMPILER, AFFILIATION Alison K. Hoagland, HABS (edited by Druscilla J. Null, HABS)		OATE 7/8/83